

The following chart provides a quick reference of the imaging lamps provided by Kodak and the scanners these consumables are used with. It is suggested that all lamps be replaced every 500 hours of operation or as necessary (i.e., as reported by the scanner, repeated image calibration failures, etc.)

NOTE: The i600 Series Scanners, i200 Series Scanners, 2500 and 1500 Scanners do not use customer-replaceable lamps.

Lamps													
CAT No.	Description	500	3500	3520	3590C	4500	5000	7500	7520	9500	9520	990	i800
816 2190	White Imaging Lamp – 16-inch											√	
912583*	White Imaging Lamp – 14-inch											√	
806 0824	Red Color Drop-Out – 14-inch											√	
813 7903	Blue Color Drop-Out 14"											√	
817 8626	Green Color Drop-Out – 14-inch											√	
162 2851	Red Imaging Element 16"											√	
813 0635	Blue Imaging Element 16"											√	
193 4140	Green Imaging Element 16"											√	
800 1370	Blue Imaging Element	√	√	√	√		√	√	√				
132 9812	Green Imaging Element	√	√	√	√		√	√	√				
126 0884	Red Imaging Element	√	√	√	√		√	√	√				
876 6545	White Imaging Lamp	√	√	√	√	√	√	√	√				√
324511	White Imaging Lamp									√	√	√	
160 0410	Blue Imaging Color Drop-out									√	√		
175 9893	Red Imaging Color Drop-out									√	√		
104 9675	Green Imaging Color Drop-out									√	√		

\* Ordered from Parts Services.